

From: Lucas Massengale
To: Brian Hunter
Sent: Thursday, December 11, 2008 7:21 AM
Subject: Servo Screw

Hi Brian,

We do not recommend the use of safety wire. This could inadvertently defeat the purpose of the shear screw and cause a dangerous loss of control in the event the servo were to lock up. We have heard of only one screw coming out, that is the one posted on the VAF forums. If you "check" the screw's tightness by tightening it a little, you will break the thread locker bond, thus allowing the screw to possibly vibrate loose. We are working on getting a different setup available soon. While we are completely confident in our current design as we have over 10,000 servos operating in the field, we will offer this update at no charge to our customers. Thanks!

Lucas Massengale
Technical Support
TruTrak Flight Systems
479-751-0250
866-878-8725
www.trutrakap.com